

Steel Mill Bearing Lube Circuit Upgrade



from this.....



- * Messy, convoluted
- * Filter changeout was difficult & complicated
- * Had to shut down to change filters
- * And didn't maintain necessary cleanliness level!

to this!



- * Duplex arrangement -- change filters without shutting down system
- * Easy to service spin-on filters
- * Donaldson garranteed cleanliness level of ISO 16/11 for 20 years! *Actual consistent level so far is ISO 13/10 !*
- * Most cost effective solution -- beating all competitors in customer's tests.

Donaldson®